


### 3 Axis 20 Amper - Robotec Unipolar Stepper Motor Driver

Mach 2 - Mach 3 - Kcam and other software product full compatible



**LPT PARALLEL PORT TO PC**  
PIN 2 STEP X-AXIS  
PIN 3 DIRECTION X AXIS  
PIN 4 STEP Y-AXIS  
PIN 5 DIRECTION Y AXIS  
PIN 6 STEP Z-AXIS  
PIN 7 DIRECTION Z AXIS

#### Not!

If connected motor voltage is a equal to Power Supply voltage, remove Current Limiter Resistor.  
Power Supply gerilimi Motorun Etiket gerilimine eşit ise Current Limiter Resistor bağlanmaz.  
Motordan daha fazla tork elde edebilmek amaçlı Power Supply gerilimi artırıldığında araya motorun etiket akımını sabit tutabilmek için Akım Sınırlama Direnci mutlaka bağlanmalıdır.  
Akım sınırlama işlemi sürücü ile değil kullanılacak motorun etiket akımı ile bağlantılıdır.